#### § 98.267

- (3) Annual phosphoric acid permitted production capacity (tons) for each wet-process phosphoric acid process line (metric tons).
- (4) Method used to estimate any missing values of inorganic carbon content or carbon dioxide content of phosphate rock for each wet-process phosphoric acid process line.
- (5) Monthly inorganic carbon content of phosphate rock for each wet-process phosphoric acid process line for which Equation Z-1a is used (percent by weight, expressed as a decimal fraction), or  ${\rm CO_2}$  (percent by weight, expressed as a decimal fraction) for which Equation Z-1b is used.
- (6) Monthly mass of phosphate rock consumed by origin, (as listed in Table Z-1 of this subpart) in production for each wet-process phosphoric acid process line (tons).
- (7) Number of wet-process phosphoric acid process lines.
- (8) Number of times missing data procedures were used to estimate phosphate rock consumption (months) and inorganic carbon contents of the phosphate rock (months).
- (9) Annual process  $CO_2$  emissions from phosphoric acid production facility (metric tons).

[74 FR 56374, Oct. 30, 2009, as amended at 75 FR 66469, Oct. 28, 2010]

# § 98.267 Records that must be retained.

In addition to the records required by  $\S98.3(g)$ , you must retain the records specified in paragraphs (a) through (c) of this section for each wet-process phosphoric acid production facility.

- (a) Monthly mass of phosphate rock consumed by origin (as listed in Table Z-1 of this subpart) (tons).
- (b) Records of all phosphate rock purchases and/or deliveries (if vertically integrated with a mine).
- (c) Documentation of the procedures used to ensure the accuracy of monthly phosphate rock consumption by origin, (as listed in Table Z-1 of this subpart).

## § 98.268 Definitions.

All terms used in this subpart have the same meaning given in the Clean Air Act and subpart A of this part.

TABLE Z-1 TO SUBPART Z OF PART 98— DEFAULT CHEMICAL COMPOSITION OF PHOSPHATE ROCK BY ORIGIN

Origin	Total carbon (percent by weight)
Central Florida	1.6
North Florida	1.76
North Carolina (Calcined)	0.76
Idaho (Calcined)	0.60
Morocco	1.56

## Subpart AA—Pulp and Paper Manufacturing

### § 98.270 Definition of source category.

- (a) The pulp and paper manufacturing source category consists of facilities that produce market pulp (i.e., stand-alone pulp facilities), manufacture pulp and paper (i.e., integrated facilities), produce paper products from purchased pulp, produce secondary fiber from recycled paper, convert paper into paperboard products (e.g., containers), or operate coating and laminating processes.
- (b) The emission units for which GHG emissions must be reported are listed in paragraphs (b)(1) through (b)(5) of this section:
- (1) Chemical recovery furnaces at kraft and soda mills (including recovery furnaces that burn spent pulping liquor produced by both the kraft and semichemical process).
- (2) Chemical recovery combustion units at sulfite facilities.
- (3) Chemical recovery combustion units at stand-alone semichemical facilities.
- (4) Pulp mill lime kilns at kraft and soda facilities.
- (5) Systems for adding makeup chemicals ( $CaCO_3$ ,  $Na_2CO_3$ ) in the chemical recovery areas of chemical pulp mills.

## § 98.271 Reporting threshold.

You must report GHG emissions under this subpart if your facility contains a pulp and paper manufacturing process and the facility meets the requirements of either §98.2(a)(1) or (a)(2).